



Continue to implement an integrated approach to bush regeneration and rehabilitation, ensuring long term sustainability.

Identify appropriate fire regimes for the park's range of vegetation communities and habitats, emphasizing protection and management of threatened species.

Repair and excavate existing sedimentation basin. Construct appropriate ramped access for easy regular maintenance.

Integrate environmental and biodiversity programmes with the objectives of fire management policy. Maintain existing mown grass within unmade section of Crown Road Reserve. Continue to rehabilitate/ enhance bushland edge condition and remove all encroachments and clumps of exotic weeds within mown area.

Enhance faunal corridors, extending indigenous street tree programme to adjoining streets, providing greater opportunities for genetic exchange with Manly Reservoir bushland.

Relocate/ reconstruct sedimentation basin up slope to allow easy regular maintenance.

Continue to address catchment management issues affecting park.

Conduct a faunal survey focussing on threatened species. Continue to control and monitor feral animal populations and promote community based environmental education programmes.

Doulton Avenue - Dresden Avenue section upgrade to main track providing bridge access over creek crossings. Retain consistency in low key materials.

Upgrade public entry/ access to playground. Implement safety recommendations for equipment.

Implement safety recommendations to playground. Re-direct overland flows on adjoining road to existing drains.

Remove weed species and plant perimeter areas with local indigenous species.

Monitor changes to creek-lines or stormwater channels including increased flow rates, gully erosion, altered drainage alignment and water quality.

Clarify park boundaries and public access on unmade road section.

Upgrade existing track/ steps between Doulton Avenue and main track. Provide entry signage to park.

Implement safety recommendations for play equipment. Provide rehabilitation planting to perimeter areas.

Maintain and upgrade existing picnic area. Relocate information board. Ensure that existing bridges and decks have adequate ramped or stepped access.

Enhance Clearview Place entry point to park including signage and rehabilitation planting. Investigate opportunities for improved disabled access.

Investigate options with Sydney Water for funding upgrading of existing steep eroded maintenance access track.

Investigate future options for upgrading steep section of track adjacent to waterfall.

Rehabilitate upper creek area above waterfall, including removal of weeds/ sediment, bank stabilization and planting.

Clarify park boundaries/ public access on unmade Crown Road Reserve.

Develop an appropriate strategic framework to address and prioritize actions relating to encroachments on public land.

Construct sedimentation basin and redirect surface water to drains. Implement playground safety recommendations and rehabilitation planting. Monitor changes to drainage lines (e.g. increased flow and erosion).

Continue to protect and enhance the park's natural bushland to provide quality settings for recreation and to promote biodiversity/ educational values.

Upgrade public access/ entry points into park, including provision of appropriate signage.

Ensure consistency in land management objectives over all the fragmented parcels of land (incl. Crown reserve, Community land and other State Government owned land).

Investigate options for consolidation of contiguous remnant bushland and protection of faunal corridors.

# Allenby Park

## Landscape Masterplan